

















# KSAARM2GR


## QUINCAILLERIE


<b>A</b>  =24	<b>H</b>  =12
<b>B</b>  =24	<b>I</b>  =2
<b>C</b>  =32 Ø8x30mm	<b>J</b>  =1
<b>D</b>  =1 GLUE	<b>K</b>  =4
<b>E</b>  =12 Ø3.5x41mm	<b>L</b>  =4
<b>F</b>  =34 Ø3.5x25mm	<b>M</b>  =6
<b>G</b>  =56 Ø3.5x16mm	<b>N</b>  =6




- 1 = 2
- 2 = 1
- 3 = 1
- 4 = 2
- 5 = 1
- 6 = 1
- 7 = 3
- 8 = 2
- 9 = 2
- 10 = 4
- 11 = 2




**A**  =24

**B**  =24

**C**  =32  
Ø8x30mm


**D**  =1  
GLUE


**E**  =8  
Ø3.5x41mm









1


**F**  =34  
Ø3.5x25mm

**G**  =16  
Ø3.5x16mm








2

- G**  =24  $\varnothing 3.5 \times 16 \text{mm}$
- H**  =12
- I**  =2
- J**  =1
- K**  =4
- M**  =6



**3**

- E**  =4  $\varnothing 3.5 \times 41 \text{mm}$
- G**  =16  $\varnothing 3.5 \times 16 \text{mm}$
- L**  =4
- N**  =6



**4**